

637 Woodbine Ave SE, Warren, OH 44483, USA

# Summary











**Q** Monitor

► Inspectify Flag

# **Repair Estimate**

\$4,000 - \$6,100

## Property Information

Home Type:	Single Family

Year Built: 1918

### Deficiencies

#### Exterior

Severity	Details	Remedy	Estimate
Repair	Downspouts had some visible damage , recommend repair/replacement of the damaged sections	Replace section(s) of gutters	\$360 - \$540
Repair	A section of fascia was missing. Repairs/replacement recommended at the affected area	Repair or replace damaged sections of the fascia	\$160 - \$240
Repair	Downspouts had some visible damage , recommend repair/replacement of the damaged sections	Replace section(s) of gutters	\$400 - \$600
Repair	Missing siding at the garage is leaving the interior exposed to weather conditions and critters. Repair(s) recommended	Install new siding	~\$4 Per sqft Est. Qty. 32.0 Total \$100 - \$160
Repair	Garage trim had some damage recommend repair	Repair or replace trim and paint to patch	\$140 - \$210

	Details	Remedy	Estimate
Repair	Siding had some damage, recommend repairing/replacing damaged sections	Replace damaged sidi paint to match	ing and ~\$6 Per sqft  Est. Qty.  10.0  Total  \$40 - \$80
Repair	Recommend repair of damaged trim by a qualified contractor	Repair or replace trim paint to patch	and \$140 - \$210
<b>Q</b> Monitor	The garage siding has moss present. This should be considered a minor defect, power washing or removing the moss is recommended	Remdiate or remove biogrowth	\$400 - \$600
aseme	nt, Foundation, Crawlspace & Structure		
everity	Details	Remedy	Estimate
			Estillate
Repair	Driveway was in poor condition recommend repair and/or replacement	Seal or re concrete o or damage	pair \$160 - \$240 cracks
Repair	Driveway was in poor condition recommend repair and/or replacement  Foundation walls were showing efflorescence and some moisture. This should be cons common for basements in this climate that do not have a waterproofing system. Mainta proper soil pitch at the exterior perimeter of the foundation, as well as keeping the gutt drain tiles clean will give rainwater its best opportunity to move away from the foundat Informational item	concrete of or damage dered Clean effloresce seal, and	pair \$160 - \$240 cracks e \$200 - \$300 ence, g where
Repair	Foundation walls were showing efflorescence and some moisture. This should be cons common for basements in this climate that do not have a waterproofing system. Mainta proper soil pitch at the exterior perimeter of the foundation, as well as keeping the gutt drain tiles clean will give rainwater its best opportunity to move away from the foundation.	dered Clean ining a effloresce ers & seal, and ion. evaluating moisture i	pair \$160 - \$240 cracks e \$200 - \$300 ence, g where

### D

Severity	Details	Remedy	Estimate
Repair	Broken/cracked glass at the window. Repairs/replacement recommended for safety considerations	Replace window	\$360 - \$540
Repair	The rear window framing is damaged and missing trim. Further review from a qualified contractor is recommended	Repair or replace trim	\$100 - \$150
Repair	Handrail missing, potential safety issue. Recommend installing handrail	Railing needs to be installed	\$280 - \$420

### Roof

Severity	Details	Remedy	Estimate
Repair	Recommend installing gutters and/or downspouts at the garage	Replace all gutters	\$400 - \$600

### Electrical

Severity	Details	Remedy	Estimate
<b>!</b> Safety	Smoke detector not visible on this level. Replacement recommended for safety considerations	Install smoke detector	\$60 - \$100

Severity	Details	Remedy	Estimate
Repair	Outlets at the kitchen wall and counter are not functional. Repairs/replacement recommended	Repair or replace outlet	~\$120 each Est. Qty. 2.0 Total \$200 - \$300
Repair	The bathroom outlet was not functional. Repairs/replacement recommended	Repair or replace outlet	\$100 - \$150
! Safety	Evidence of rust in panel. Further review from a licensed electrician is recommended	Repair or replace breakers	\$160 - \$240
! Safety	Electrical Panel - Missing cover: Missing Dead Front	Install New Dead Front Cover	\$100 - \$150
<b>Q</b> Monitor	The bathroom overhead lighting was not functional. Repairs/replacement recommended	Repair light	\$70 - \$110
<b>Q</b> Monitor	The bathroom overhead lighting was not functional. Repairs/replacement recommended	Repair light	\$70 - \$110